

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
1	2840	011266906 / 011585967	(Pri #1 OTA) 4th Stage COMPRESSOR-ROTOR, ACFT GAS TURBINE (\$5,678.83) (Line 236) P/N 34946 / 37253	100%	1	1%	0	0	FHZ
2	2840	012352277	<b>(Teledyne)</b> Case, 2nd Stage Turbine, (2nd Stg Turb Nozzle Assy) (\$12,383.14) P/N 36847	100%	1	10%	1	1	FHZ
3	2840	011585959	(Pri #2 OTA) INTERSTAGE HOUSING (\$4,140.60) P/N 37227/37428/37441	UNK	1	UNK	0	0	FHZ
4	2840	011206306	SUPPORT-SEAL RETAINER (\$355.16) P/N 29558	100%	1	15%	1.5	4	DLA
5	2840	011206399	SHIELD, HEAT, #4 Carbon Seal (\$187.14) P/N 36598	100%	1	90%	9	7	DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
6	2915	011273194	SLINGER-FUEL (\$1,979.33) P/N 36944	100%	1	80%	8	5	DLA
7	2840	011273201	SEAL, METALLIC, ACFT, #3 Brng Rtnr (\$629.73) P/N 23252	100%	1	8%	0.8	2	DLA
8	3020	011311810	GEAR-BEVEL (\$3,156.14) P/N 29566	100%	1	3%	0.3	2	DLA
9	2915	012108585	FUEL CONTROL-MAIN-TURBINE ENGINE (\$8,160.26) P/N 39564/8601- 102/46971/8601-106....	100%	1	93%	9.3	12.6	FHZ
10	5365	012963311	SPACER-RING (\$61.27) P/N 23514-05	100%	1	1%	0.1	10	DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
11	5310	011297610	NUT-PLAIN-HEXAGON (1st Stage) (\$30.05) P/N 23538	100%	1	34%	3.4	11	DLA
12	5365	012963312	SPACER-RING (\$31.14) P/N 23514-06	100%	1	1%	0.1	10	DLA
13	5365	012963315	SPACER-RING (\$10.93) P/N 23514-09	100%	1	1%	0.1	10	DLA
14	2935	012930243	(DLA/DOE) COOLER-LUBRICATING OIL-ENGINE (\$1,375.56) P/N 41302/UA538245-4	100%	1	67%	6.7	4	DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
15	2840	011273342	HP SHAFT-TURBINE-AIRCRAFT GAS TURBINE (\$47,703.17) P/N 34977	100%	1	25%	2.5	5	FHZ
16	2840	011266908	(OTA)3rd Stage Rotor-Turbine- AIRCRAFT GAS TURBI (\$24,725.05) P/N 23494	100%	1	1%	0.1	1	FHZ
17	5365	012963313	SPACER-RING (\$12.14) P/N 23514-07	100%	5	5%	2.5	16	DLA
18	5307	011272724	STUD-LOCKED IN (\$4.75) P/N SFC164SUM-8//88231	100%	24	50%	120	60	DLA
19	5307	011768431	STUD-LOCKED IN (\$51.12) P/N 88084/9117M42P07/SFC250SU M17	100%	2	8%	1.6	13	DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
20	5330	013066915	Seal Ring, Metal (Sleeve, #3 Turbine Nozzle Repair) (\$709.18) P/N 23242 / C-4340	100%	1	50%	5		DLA
21	5365	012963308	SPACER-RING (\$39.35) P/N 23514-02 (IPV Item) F107, BSL 458, BIN 3F07	100%	1	4%	0.4	12	DLA
22	5330	011287084	SEAL-PLAIN (\$28.77) P/N 29855 (IPV Item) F107, BSL 458, BIN 3J10 BSL 527 BIN A233	100%	2	100%	20	26	DLA
23	2840	011267654	R. COLLAR-ENGINE MOUNT (\$13.25) P/N 36385	100%	1	1%	0.1	8	DLA
24	5342	011267657	L. Engine Mount (\$325.98) P/N 36120	100%	1	1%	0.1	5	DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
25	5342	011267666	R. Engine Mount (\$288.23) P/N 36384	100%	1	1%	0.1		DLA
26	2840	011266916	CHAMBER-COMBUSTION- AIRCRAFT GAS (\$10,499.65) P/N 36296	100%	1	10%	0	2	FHZ
27	5315	016523947	PIN, SHOULDER, HEADLE (\$17.86) P/N 88082	100%	1	0%	0	0	DLA
28	2840	011266923	NOZZLE - #3 TURBINE-ACFT (\$3,103.51) P/N 34668	100%	1	10%	1	1	FHZ
29	5305	011277076	SCREW-MACHINE (\$11.06) P/N MS9487-12 (IPV Item) <a href="#">F107, BSL 780, BIN A256</a>	100%	4	100%	40	56	DLA
30	5310	005103826	NUT-SELF-LOCKING-EXTENDED WASHER (\$3.99) P/N H35-836 (IPV Item) <a href="#">F107, BSL 527, BIN A239</a>	100%	29	100%	290	175	DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
31	5360 / Alt 5360	011463172 / 011291805	SPRING-HELICAL-COMPRESSION (\$4.05) ALT=(\$336.78) P/N 23798 / 24954	100%	1	100%	10	12	DLA
32	5320	001515520	RIVET-BLIND (\$0.88) P/N MLSP-B04-03 / GR500L4-03 / NAS1919B04-03	100%	42	2%	8.4	6000	DLA
33	3130	011266929	(DLA/DOE) LINER-BEARING HOUSING (\$374.69) P/N 23999	100%	1	4%	0.4	2	DLA
34	3120	011267592	BEARING-SLEEVE (\$119.76) P/N 36110	100%	1	4%	0.4	2	DLA
35	5340	010335076	CLAMP-LOOP (\$1.40) P/N NAS1715C6K / NAS1715C6KW	100%	3	1%	0.3	865	DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
36	5305	004476532	SCREW-MACHINE (\$1.16) P/N 90744 / MS9555-07 (IPV Item) F107, BSL 527, BIN A253	100%	54	30%	162	636	DLA
37	2840	011206310	LUG-HEAT SHIELD (\$6.78) P/N 34484	100%	5	1%	0.5	10	DLA
38	5331	001799369	O-RING (\$0.19) P/N 6012T59G01	100%	1	100%	10	33	DLA
39	5305	011267311	SCREW-MACHINE (\$14.93) P/N MS9488-03	100%	2	0%	0	0	DLA
40	5331	011264557	O-RING (\$57.03) P/N 27289 (IPV Item) F107, BSL 527, BIN A234	100%	1	100%	10	43	DLA
41	3110	011252031	BEARING-BALL-DUPLEX (\$2,525.64) P/N 22098/29845/SFZ887MX1/5544 91/46898	100%	1	8%	0.8		DLA



# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
42	4320	011339882	PUMP-ROTARY (\$4,666.42) P/N 36365 / RR36920B	100%	1	91%	9.1	12	FHZ
43	3110	011267591	SEAT-BEARING, #2 Brng Rtnr (\$784.49) P/N 29520	100%	1	4%	0.4	2	DLA
44	3130	011267648	HOUSING-BEARING UNIT, #1 Brng Rtnr (\$478.10) P/N 23395	100%	1	4%	0.4		DLA
45	5365	011268738	SPACER-RING (\$22.10) P/N 34643	100%	2	45%	9		DLA
46	3130	011270869	#2 HOUSING-BEARING UNIT (\$490.56) P/N 29707	100%	1	6%	0.6		DLA
47	3040	011294632	SHAFT-SHOULDERED (\$204.90) P/N 24915	100%	1	3%	0.3		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
48	3020	011294689	(DLA/DOE) GEAR-BEVEL (\$595.58) P/N 36373	100%	1	4%	0.4		DLA
49	5330	011302140	RETAINER-PACKING (\$432.97) P/N 34952	100%	1	5%	0.5		DLA
50	4730	010502489	CLAMP-HOSE (\$1.86) P/N NH102300-0125	100%	1	4%	0.4		DLA
51	5330	010765701	PACKING-PREFORMED (\$1.46) P/N M83248/1-026/NAS1593- 212/S9413-026 (IPV Item) F107 BSL 527 BIN A246	100%	2	100%	20		DLA
52	2840	011215684	RESTRICTOR-AIRFLOW (\$2.14) P/N 29067	100%	5	1%	0.5		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
53	4730	000077411	UNION-TUBE (\$54.64) P/N 25104	100%	1	1%	0.1		DLA
54	2840	011267652	RETAINER-INTERFACE (\$178.95) P/N 27093	100%	1	1%	0.1		DLA
55	2840	011267664	RETAINER-INTERFACE TUBE (\$30.82) P/N 29865	100%	1	4%	0.4	2	DLA
56	3020	011267697	GEAR-BEVEL (\$6,147.00) P/N 24884	100%	1	4%	0.4		DLA
57	5310	011268473	WASHER (\$19.41) P/N 22488	100%	6	68%	40.8	56	DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
58	5365	011268739	SPACER-RING (\$6.30) P/N 34642	100%	2	4%	0.8	18	DLA
59	5305	011268801	SCREW-MACHINE (\$8.39) P/N MS9554-07	100%	6	13%	7.8	12	DLA
60	5315	011271008	PIN-STRAIGHT-HEADLESS (\$17.47) P/N 34425	100%	6	1%	0.6		DLA
61	5365	011272723	RING-LOCK (\$13.66) P/N SFC164SUM-7//88230	100%	2	7%	1.3	8	DLA
62	5340	011272725	CLAMP-LOOP (\$10.00) P/N 36391	100%	2	0%	0	4	DLA
63	4730	011273091	STRAINER ELEMENT-SEDIMENT (\$144.30) P/N 29825 /39616	100%	1	4%	0.4	3	DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
64	2840	011273193	SEAL RING-LABYRINTH-AIRCRAFT GAS (\$130.51) P/N 34985	100%	1	70%	7	3	DLA
65	5325	016517441	Ring Retaining (\$6.23) P/N 27722	100%	1	0%	0		DLA
66	5310	011278332	NUT (\$22.35) P/N 88268 / H33-8	100%	1	100%	10	6	DLA
67	2840	011287233	SEAL RING-LABYRINTH-AIRCRAFT GAS (\$117.83) P/N 24888	100%	1	17%	1.7	6	DLA
68	1336	011287253	TANK ASSEMBLY-OXYGEN (\$932.15) P/N 29667 / 23111368	100%	1	30%	3	FGZ	

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
69	5365	012305296	SPACER-RING (\$41.12) P/N 36141-02	100%	1	0%	0		DLA
70	4710	011288158	TUBE-BENT-METALLIC (\$1013.33) P/N 23810	100%	1	4%	0.4	2	DLA
71	9905	011368902	BAND-MARKER (\$0.79) P/N 22853	100%	1	0%	0	2	DLA
72	5310	011288168	WASHER-LOCK (\$) P/N 22240	100%	6	1%	0.6		DLA
73	5365	011295376	SPACER-PLATE (\$4.49) P/N 27614	100%	2	0%	0	4	DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
74	7690	012161081	MARKER-IDENTIFICATION (\$1,380.18) P/N 15860	100%	1	0%	0	2	DLA
75	2840	011433834	(OTA) 2nd Stage Rotor-Turbine- AIRCRAFT GAS TURBI (\$2,6062.31) P/N 37909	100%	1	1%	0.1	1	FHZ
76	3120	012696385	BUSHING-SLEEVE (\$148.24) P/N 38108	100%	3	0%	0	6	DLA
77	5340	11288235	BRACKET-ANGLE (\$394.18) P/N 36256	100%	1	1%	0.1	2	DLA
78	4710	011288434	TUBE ASSEMBLY-METAL- BRANCHED (\$375.65) P/N 36838	100%	1	1%	0.1	2	DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
79	5340	011288599	CLIP-SPRING TENSION (\$9.44) (P/N 22714)	100%	1	1%	0.1	2	DLA
80	5365	011288607	SHIM (\$225.39) (P/N 22450)	100%	1	1%	0.1	4	DLA
81	5365	011288608	SHIM (\$15.37) (P/N 22451)	100%	1	1%	0.1	4	DLA
82	5365	011288609	SHIM (\$33.47) (P/N 22452)	100%	1	1%	0.1	2	DLA
83	5365	011288611	SHIM (\$11.54) (P/N 22454)	100%	1	0%	0	4	DLA



# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
84	4710	011288621	TUBE ASSEMBLY-METAL (\$448.79) (P/N 23511)	100%	1	1%	0.1	2	DLA
85	5310	011291610	NUT-SELF-LOCKING-EXTENDED WASHER (\$5.64) (P/N 24640)	100%	39	100%	390	5	DLA
86	1336	011295283	CARTRIDGE-ENGINE STARTER (\$774.35) (P/N 13144-1)	100%	1	30%	3	FGZ	
87	5305	011312169	SCREW-MACHINE (\$10.67) P/N MS9712-04 <a href="#">(IPV Item)</a> <a href="#">F107 BSL 527 BIN A262</a>	100%	61	100%	610	812	DLA
88	4720	011317149	HOSE-PREFORMED (\$371.43) (P/N 232-30827-2)	100%	1	5%	0.5	2	DLA
89	4730	011318413	COUPLING-TUBE (\$210.91) (P/N 29822)	100%	2	1%	0.2	4	DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
90	4730	011327695	TEE-TUBE TO BOSS (\$85.96) (P/N 34933)	100%	1	1%	0.1	2	DLA
91	5310	011420691	WASHER-RECESSED (\$240.37) (P/N 22618)	100%	1	100%	10	7	DLA
92	5331	000200203/001031 986	O-RING (\$0.13) (P/N AS3208-04) (IPV Item) F107 BSL 508 BIN 4G09	100%	6	0%	0		DLA
93	2840	011433833	RETAINER ASSEMBLY (\$8.20) (P/N 36829)	100%	1	2%	0.2	2	DLA
94	3110	011485250	SEAT-BEARING (\$68.30) (P/N 37079)	100%	1	1%	0.1	0	DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
95	4710	011611721	TUBE ASSEMBLY-METAL (\$599.67) (P/N 36557)	100%	1	1%	0.1	4	DLA
96	4730	011885883	TEE-TUBE (\$32.07) (P/N AN834-3J)	100%	1	1%	0.1	1	DLA
97	5365	012316025	SPACER-RING (\$10.48) (P/N 36141-07)	100%	1	3%	0.3	3	DLA
98	5365	012316026	SPACER-RING (\$10.42) (P/N 36141-08)	100%	1	33%	3.3	2	DLA
99	4730	004361962	SEAL-CONICAL-FLARED TUBE FITTING (\$13.66) P/N 29093	100%	8	100%	80		DLA
100	3040	12622664	GEARSHAFT-SPUR (\$356.98) (P/N 37247)	100%	1	1%	0.1	0	DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
101	9905	012945026	PLATE-IDENTIFICATION (\$1.75) (P/N 29475)	100%	1	1%	0.1	0	DLA
102	9905	012945318	PLATE-IDENTIFICATION (\$3.50) (P/N 15311)	100%	1	1%	0.1	0	DLA
103	5340	011288595	Strap, Retaining (\$26.13) P/N 29607	100%	8	0%	0		DLA
104	5315	000569386	PIN-STRAIGHT-HEADLESS (\$0.16) P/N 34425	100%	1	1%	0.1		DLA
105	5340	000602095	CLAMP-LOOP (\$0.37) P/N 466SS6	100%	3	2%	0.6		DLA
106	5306	000800094	BOLT-MACHINE (\$0.46) P/N MS9489-05 (IPV Item) F107 BSL 458 BIN 3F01	100%	2	0%	0		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
107	5306	000800099	BOLT-MACHINE (\$0.52) P/N MS9489-06 <a href="#">(IPV Item)</a> <a href="#">F110 BSL 429 BIN 7B08</a>	100%	1	1%	0.1		DLA
108	5306	000800133	BOLT-MACHINE (\$0.87) P/N MS9489-04	100%	1	1%	0.1		DLA
109	4730	001022676	NIPPLE-BOSS (\$6.57) P/N AN815-5J	100%	1	1%	0.1		DLA
110	5306	001066321	BOLT-MACHINE (\$0.81) P/N MS9556-07 <a href="#">(IPV Item)</a> <a href="#">F107 BSL 458 BIN 3J03</a>	100%	8	0%	0		DLA
111	5306	001138362	BOLT-MACHINE (\$0.76) P/N MS9556-06 <a href="#">(IPV Item)</a> <a href="#">F107 BSL 458 BIN 2E14</a>	100%	1	0%	0		DLA
112	5306	001186450	BOLT-MACHINE (\$2.37) P/N MS21279-04	100%	1	0%	0		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
113	5310	001243025	WASHER-FLAT (\$0.04) P/N MS9549-07	100%	2	100%	20		DLA
114	5310	001411795	WASHER-FLAT (\$0.01) P/N AN960-416 (IPV Item) F107 BSL 458 BIN 3H05	100%	2	0%	0		DLA
115	5365	001416943	BUSHING-NONMETALLIC (\$0.63) P/N MS39056-7	100%	1	0%	0		DLA
116	5310	001499130	WASHER-FLAT (\$3.61) P/N MS20002-6 (IPV Item) F107 BSL 458 BIN 3H06	100%	5	0%	0		DLA
117	5310	001499146	WASHER-RECESSED (\$5.97) P/N MS20002-C6 (IPV Item) F107 BSL 458 BIN 3F08	100%	2	0%	0		DLA
118	5340	001634304	CAP-PROTECTIVE-DUST AND MOISTURE (\$2.54) (P/N NAS814-4) (IPV Item) F107 BSL 458 BIN 3C09	100%	1	0%	0		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
119	5331	001651936	O-RING (\$1.18) P/N MS9388-159 (IPV Item) F107 BSL 458 BIN 2H03 BSL 527 BIN A245	100%	1	0%	0		DLA
120	5331	001660966	O-RING (\$0.09) P/N M83248/1-007	100%	1	100%	10		DLA
121	5331	001660968	O-RING (\$0.10) P/N 10159809, J221P009 (IPV Item) F107 BSL 458 BIN 2G06 BSL 527 BIN A241	100%	6	0%	0		DLA
122	5331	001660969	O-RING (\$0.12) P/N MS28782-2, 010-17507 (IPV Item) F107 BSL 458 BIN 1H03 BSL 508 BIN 4D03	100%	3	0%	0		DLA
123	5331	001660975	O-RING (\$0.12) P/N NAS1593-011, MS9388-011 (IPV Item) F107 BSL 458 BIN 1H04 BSL 527 BIN A221	100%	4	0%	0		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
124	5331	001660980	O-RING (\$0.13) P/N 20012-9, 1531758-16 (IPV Item) F107 BSL 458 BIN 2G08 BSL 527 BIN A218	100%	2	0%	0		DLA
125	5331	001660991	O-RING (\$0.12) P/N 20015-9, 039-705-0002 (IPV Item) F107 BSL 458 BIN 2H02	100%	1	0%	0		DLA
126	5331	001660992	O-RING (\$0.10) P/N 016-19357, AS3209-016 (IPV Item) F107 BSL 458 BIN 2G09 BSL 527 BIN A106	100%	2	0%	0		DLA
127	5331	001660993	O-RING (\$0.10) P/N 2-017V884-75, M83248/1-017 (IPV Item) F107 BSL 458 BIN 1H07 BSL 508 BIN 4G03	100%	3	0%	0		DLA
128	5331	001660996	O-RING (\$0.12) P/N S9413-019, AS568-019 (IPV Item) F107 BSL 458 BIN 2H01 BSL 508 BIN 4D01 BSL 527 BIN A248	100%	3	0%	0		DLA



# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
129	5331	001661001	O-RING (\$0.16) P/N 2-020V1164-75, NAS1593-020 (IPV Item) BSL 458 BIN 2F06 F107	100%	1	0%	0		DLA
130	5331	001661022	O-RING (\$0.19) P/N ST3001-025, 649-393-025-0, MIL-R-83248 (IPV Item) F107 BSL 458 BIN 1H08	100%	5	0%	0		DLA
131	5331	001661025	O-RING (\$0.19) P/N J221P026, 903231C1, 159460026 (IPV Item) F107 BSL 458 BIN 2H05	100%	2	0%	0		DLA
132	5331	001661030	O-RING (\$0.21) P/N 2-028V1164-75, 568027-2, ST1000-028 (IPV Item) F107 BSL 458 BIN 3J09	100%	1	0%	0		DLA
133	5331	001661041	O-RING (\$0.48) P/N J221P041, 431384ITEM 56, M83248/1-041 (IPV Item) F107 BSL 458 BIN 2F02	100%	1	0%	0		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
134	5331	001661046	O-RING (\$0.61) P/N J221P042, 201113-09, S9413-042 (IPV Item) F107 BSL 458 BIN 2F01	100%	2	0%	0		DLA
135	5331	001668390	O-RING (\$0.30) P/N A1005816, ST1050-030, 25283A (IPV Item) F107 BSL 458 BIN 1J03	100%	3	0%	0		DLA
136	5331	001668391	O-RING (\$0.25) P/N S9413-031, J221P031, 0001- 0039R (IPV Item) F107 BSL 458 BIN 1H10	100%	2	0%	0		DLA
137	5331	001668394	O-RING (\$0.40) P/N J221P034, S9413-034, MILR83248 (IPV Item) F107 BSL 458 BIN 2G04	100%	2	0%	0		DLA
138	5310	001670835	WASHER-FLAT (\$0.10) P/N 200151, 911244, 7402359 (IPV Item) F107 BSL 458 BIN 3H09	100%	9	0%	0		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
139	5331	001675124	O-RING (\$0.39) P/N J221P139, 21340 FIND 42, M83248/1-139 (IPV Item) F107 BSL 458 BIN 2J04	100%	1	0%	0		DLA
140	5331	001675145	O-RING (\$2.31) P/N R149P262A, M83248/1-262, MS9388-262 (IPV Item) F107 BSL 458 BIN 3G03	100%	1	0%	0		DLA
141	5331	001675165	O-RING (\$0.13) P/N 3011660, J221P901, M83248/1-901 (IPV Item) F107 BSL 458 BIN 2F05	100%	2	0%	0		DLA
142	5331	001675166	O-RING (\$0.15) P/N 20905-12, 305000-5, M3102865 (IPV Item) F107 BSL 458 BIN 2H04	100%	1	0%	0		DLA
143	5331	001675175	O-RING (\$0.20) P/N 238290-912, 366-59531 ITEM7, MIL-R-83248 (IPV Item) F107 BSL 458 BIN 3H01	100%	1	0%	0		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
144	5305	001701546	SCREW-MACHINE (\$1.67) P/N MS9564-04	100%	5	1%	0.5		DLA
145	5305	001738117	SCREW-MACHINE (\$1.48) P/N MS9555-02, 10125036 <i>(IPV Item)</i> <i>F107 BSL 458 BIN 3E11</i>	100%	2	0%	0		DLA
146	5305	001744605	SCREW-MACHINE (\$22.40) P/N MS9554-03	100%	2	4%	0.8		DLA
147	5340	001774113	CLAMP-LOOP (\$0.55) P/N NAS1715C4T, 5047C4G	100%	6	1%	0.6		DLA
148	5340	001774120	CLAMP-LOOP (\$0.58) P/N NAS1715C17T	100%	1	15%	1.5		DLA
149	4730	001829021	NIPPLE-TUBE (\$4.30) P/N 124-3003, AN815-6C, AS4841MS24392J6	100%	1	1%	0.1		DLA
150	5331	002118213	O-RING (\$0.33) P/N 11-106914, 568-914, AMS7276, AS568-914, MILR83248, NAS1595-14	100%	1	0%	0		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
151	5331	002317701	O-RING (\$0.19) P/N 10159961, 59412-554, M25988/2-904, MIL-R-25988, S9412-554	100%	1	0%	0		DLA
152	4730	002385347	CAP-TUBE (\$5.50) P/N 10111310, AN929A2K, AS4841, MIL-F-5509	100%	1	1%	0.1		DLA
153	5331	002534844	O-RING (\$0.16) P/N MIL-R-25988, S8057AP6, S9005E11, S9412-011, S9413- 011	100%	1	0%	0		DLA
154	5331	002799322	O-RING (\$0.30) P/N 10163255, 3-908-11647, 908-11647, MIL-R-25988 <a href="#">(IPV Item)</a> <a href="#">F107 BSL 458 BIN 3H03</a>	100%	1	0%	0		DLA
155	5331	002881976	O-RING (\$0.21) P/N 035022, 3-904/L677-70, 571034-04, 99-4602-04, M25988-1-904 <a href="#">(IPV Item)</a> <a href="#">F107 BSL 458 BIN 1H01</a>	100%	1	0%	0		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
156	5331	003431035	O-RING (\$0.19) P/N 010-11647, 10159953, 16606A79-5, 2-010L375-70, M25988-1-010 (IPV Item) F107 BSL 458 BIN 3E08	100%	1	0%	0		DLA
157	5305	003649731	SCREW-MACHINE (\$492.69) P/N MS9488-05	100%	2	1%	0.2		DLA
158	5320	004255327	RIVET-SOLID (\$3.21) P/N MS9319-002	100%	1	1%	0.1		DLA
159	2915	012418855	VALVE-FUEL CONTROL, (\$1817.08) P/N 29593	100%	1	7%	0.7	8	FHZ
160	5340	004376461	CAP-PROTECTIVE-DUST AND MOISTURE (\$5.42) P/N 10117363, 97121-422R, EC- 22MS90376-22R, P10555 (IPV Item) F107 BSL 458 BIN 3D06	100%	1	0%	0		DLA
161	5305	004484707	SCREW-EXTERNALLY RELIEVED BODY (\$1.85) P/N MS9555-05	100%	5	1%	0.5		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
162	4730	004697820	CLAMP-HOSE (\$0.34) P/N 10108388, 2954, 38290, 6207, 6604, AR48236, MMP92368	100%	2	1%	0.2		DLA
163	5340	004711913	CLAMP-LOOP (\$0.33) P/N AS5587C04, MS21103-4	100%	2	1%	0.2		DLA
164	5340	004818934	CAP-PROTECTIVE-DUST AND MOISTURE (\$2.09) P/N 4270-14Y, 5D0377-14Y, 701- 1912, AS90376-14Y, FC713, MS90376-14Y (IPV Item) <a href="#">F107 BSL 458 BIN 3D08</a>	100%	2	0%	0		DLA
165	4730	004854788	NIPPLE-BOSS (\$5.15) P/N AS18280, MS21902W8 (IPV Item) <a href="#">F107 BSL 458 BIN 3E03</a>	100%	1	0%	0		DLA
166	5310	004906482	NUT-PLAIN-HEXAGON (\$5.15) P/N MS9356-06 (IPV Item) <a href="#">F107 BSL 527 BIN A243</a>	100%	6	1%	0.6		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
167	5340	004935835	CAP-PROTECTIVE-DUST AND MOISTURE (\$2.99) P/N 10117377, 70206, 97121-414R, MS90376-14R, NAS831-14 (IPV ITEM) <a href="#">F107 BSL 458 BIN 3D04</a>	100%	1	0%	0		DLA
168	5306	004968942	BOLT-MACHINE (\$1.28) P/N 10114292, MS9556-11, R1453P011 (IPV ITEM) <a href="#">F107 BSL 458 BIN 3J04</a>	100%	11	0%	0		DLA
169	5331	004985733	O-RING (\$0.21) P/N 10163876, 19483, 78146-011, MIL-R-25988/1-011, SG3939PC28 (IPV ITEM) <a href="#">F107 BSL 458 BIN 2J03</a>	100%	1	0%	0		DLA
170	5310	005157449	WASHER-FLAT (\$1.18) P/N 03014-44, 153-0013-011, 186439, 2411796, AN960C416L	100%	9	1%	0.9		DLA
171	5340	012226991	CAP-PROTECTIVE-DUST AND MOISTURE (\$0.19) (P/N 25392)	100%	2	7%	1.4	4	DLA



# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
172	4730	005418287	REDUCER-BOSS (\$4.36) P/N 731798-2, AN919-2C, AS4841, MS24399J3 <a href="#">(IPV ITEM)</a> <a href="#">F107 BSL 458 BIN 2G03</a>	100%	1	0%	0		DLA
173	5340	05700435	CLAMP-LOOP (\$0.51) P/N NAS1715C3K	100%	1	7%	0.7		DLA
174	5325	005947825	INSERT-SCREW THREAD (\$2.09) P/N 1001872-007, 540725-131, 7792303-4, 873421-00, MIL-I- 45932/1	100%	1	0%	0		DLA
175	5306	006397587	BOLT-INTERNAL WRENCHING (\$4.11) P/N 330-1686-040, MS20006-20 <a href="#">(IPV ITEM)</a> <a href="#">F107 BSL 458 BIN 3J12</a>	100%	2	0%	0		DLA
176	5340	006631970	CLAMP-LOOP (\$1.64) P/N 10117421, AN742F3, MS21103-3	100%	1	7%	0.7		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
177	5310	006853744	WASHER-FLAT (\$1.49) P/N 004-003081-025, 101967-135, 10975113, 153-0013-008, AN960C8 (IPV ITEM) F107 BSL 458 BIN 3F03 BSL 408 BIN 4F06	100%	25	0%	0		DLA
178	5306	007023998	BOLT-MACHINE (\$13.74) P/N NAS1304-5, NAS498 (IPV ITEM) F107 BSL 458 BIN 3H10	100%	1	0%	0		DLA
179	4730	007201508	CAP-TUBE (\$2.46) P/N 0717-4, 10108439, 27G3191-1, 8431409, AN929-4J	100%	1	1%	0.1		DLA
180	4730	007629456	PLUG-TUBE FITTING-THREADED (\$5.45) P/N AN806-6K, AS4841, MS24404J6, MS24404K6	100%	1	1%	0.1		DLA
181	5305	007815664	SCREW-MACHINE (\$4.48) P/N 10125490, 112-1055-049, 7903133-48, 859959-00, MS24693-C271 (IPV Item) F107 BSL 458 BIN 3J02	100%	1	0%	0		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
182	5310	007819483	WASHER-FLAT (\$0.73) P/N 004-002894-061, 186445, 2504638-13, 418154-6, NAS620C10L (IPV Item) F107 BSL 458 BIN 3F02 BSL 527 BIN A237	100%	4	0%	0		DLA
183	5310	007838778	WASHER-FLAT (\$0.06) P/N 202-16-08, MS9321-08	100%	26	1%	2.6		DLA
184	5325	008046856	RING-RETAINING (\$6.72) P/N 0218633-6856, 10056125, 103A204-1, 12Z5010-1, 443338, N5000-25HSTB	100%	1	1%	0.1		DLA
185	5310	008071467	NUT-SELF-LOCKING-EXTENDED WASHER (\$32.10) (IPV Item) F107 BSL 458 BIN 3J11	100%	1	100%	10		DLA
186	5310	008101786	NUT-SELF-LOCKING-EXTENDED WASHER P/N 10195373/12387354/13- 21816 (\$53.39) (IPV Item) F107 BSL 458 BIN 3F12	100%	4	0%	0		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
187	5315	008238740	PIN-SPRING P/N 012-062-0375/0495-5/10122750 (\$3.14) (IPV Item) <span style="float: right;">F107</span> BSL 458 BIN 2E11	100%	1	0%	0		DLA
188	5315	008263251	PIN-SPRING P/N 10121087/2640-682-10-ITEM 43 (\$2.75) (IPV Item) F107 BSL 458 BIN 2G01	100%	1	0%	0		DLA
189	5310	008387285	WASHER-FLAT (\$0.04) P/N MS9549-12	100%	1	1%	0.1		DLA
190	5310	008443302	NUT-SELF-LOCKING-EXTENDED WASHER P/N 10121763/2523107/2529611 (\$0.49) (IPV Item) F107 BSL 458 BIN 3J13 BSL 508 BIN 4F07 BSL 527 BIN A236	100%	17	0%	0		DLA
191	5310	008444872	NUT-SELF-LOCKING-EXTENDED WASHER P/N 10121787/2638719/268719 (\$0.42) (IPV Item) F107 BSL 458 BIN 2E15 BSL 527 BIN A232	100%	11	0%	0		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
192	5325	008644958	INSERT-SCREW THREAD (\$0.90) P/N 10018772- 003/10173119/30-317-604-02	100%	2	1%	0.2		DLA
193	4730	008758264	NIPPLE-BOSS (\$4.66) P/N 10163749/2308001PC93	100%	1	0%	0		DLA
194	5310	008783291	NUT-SELF-LOCKING-EXTENDED WASHER P/N 10121786/206419/2523333 (\$0.46) <a href="#">(IPV Item)</a> <a href="#">F107 BSL 458 BIN 3H11</a>	100%	2	0%	0		DLA
195	5310	008787196	NUT-SELF-LOCKING-EXTENDED WASHER P/N 10121788/2637150/645403- 08 (\$0.58) <a href="#">(IPV Item)</a> <a href="#">F107 BSL 458 BIN 2E18</a>	100%	8	0%	0		DLA
196	5310	008810943	NUT-SELF-LOCKING-EXTENDED WASHER P/N 10121791/2627596 (\$0.94) <a href="#">(IPV Item)</a> <a href="#">F107 BSL 458 BIN 3H07</a>	100%	1	0%	0		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
197	5325	009007511	RING-RETAINING (\$2.61) P/N 3000-X193-SS2/MS16625-4193	100%	1	100%	10		DLA
198	5305	009022136	SCREW-MACHINE (\$3.58) P/N 112-1055-030/604-5529702ITE (IPV ITEM) F107 BSL 458 BIN 3F11	100%	4	0%	0		DLA
199	4730	009083193	CLAMP-HOSE (\$0.33) P/N MS35842-12 (IPV ITEM) F107 BSL 458 BIN 2G02	100%	1	0%	0		DLA
200	4730	009083194	CLAMP-HOSE (\$1.31) P/N 0000265/0921911-4/1002652 (IPV ITEM) F107 BSL 458 BIN 3J05	100%	1	0%	0		DLA
201	4730	009098627	CLAMP-HOSE (\$0.34) P/N 0000306/006847/10036S	100%	2	1%	0.2		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
202	5310	009265913	NUT-PLAIN-HEXAGON (\$2.69) P/N 013-0002-30/114494/2650515-6 (IPV ITEM) F107 BSL 458 BIN 2E16	100%	1	0%	0		DLA
203	5315	009513215	PIN-STRAIGHT-HEADLESS (\$0.21) P/N 10122830/104A901903	100%	2	0%	0		DLA
204	5305	009582918	SCREW-MACHINE (\$3.09) P/N 044-312-0034/10114739	100%	2	1%	0.2		DLA
205	5975	009846582	STRAP-TIEDOWN-ELECTRICAL COMPONE (\$1.12) P/N MS3367-1-0/10134324/10503296 (IPV ITEM) F107 BSL 458 BIN 2D04	100%	13	0%	0		DLA
206	5310	009938703	WASHER-FLAT (\$0.04) P/N MS9549-08	100%	3	1%	0.3		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
207	5330	009940721	PACKING-PREFORMED (\$6.46) P/N VSF1015N54/AP50N5	100%	1	0%	0		DLA
208	5331	010050512	O-RING (\$2.22) P/N 2-176V0747-75 (IPV ITEM) F107 BSL 458 BIN 3G04	100%	1	0%	0		DLA
209	5331	010050517	O-RING (\$0.19) P/N 2-201V0747-75	100%	3	5%	1.5		DLA
210	5331	010054064	O-RING (\$0.19) P/N 3-2L375-7 (IPV ITEM) F107 BSL 458 BIN 1C01	100%	1	0%	0		DLA
211	5331	010063931	O-RING (\$0.60) P/N 2-040 77-545-75 (IPV ITEM) F107 BSL 458 BIN 1C03	100%	1	0%	0		DLA



## F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
212	5365	010101292	PLUG-MACHINE THREAD (\$2.92) P/N MS9954-04 (IPV ITEM) <span style="color: blue;">F107</span> BSL 458 BIN 3E10	100%	2	0%	0		DLA
213	4730	010126998	SEAL-CONICAL-FLARED TUBE FITTING (\$23.50) P/N VSF1015/DY90/	100%	8	100%	80		DLA
214	5315	010150756	PIN-SPRING (\$0.04) P/N MS51987-369	100%	1	1%	0.1		DLA
215	5340	010152253	CLAMP-LOOP (\$1.03) P/N NAS1715C5K	100%	1	0%	0		DLA
216	5305	010157088	SCREW-MACHINE (\$1.88) P/N MS9564-02	100%	3	1%	0.3		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
217	4730	010165674	SEAL,CONICAL,FLARED TUBE FITTING (\$12.47) P/N VSF1015/4730010165674/6310 069-003	100%	2	89%	17.8		DLA
218	5331	010167550	O-RING (\$3.79) P/N 0001.0038.R/20213PC16 (IPV ITEM) F107 BSL 508 BIN 4G05	100%	4	0%	0		DLA
219	5330	010193239	SEAL-PLAIN ENCASED (\$10.48) P/N 23808/23811	100%	1	1%	0.1		DLA
220	5340	010342851	BRACKET-ANGLE (\$0.78) P/N MS9600-010	100%	1	0%	0		DLA
221	6150	010499305	LEAD-ELECTRICAL (\$8.61) P/N 4F2F/740D-20-8/BAC-J40D-20-8 (IPV ITEM) F107 BSL 458 BIN 3H12	100%	1	100%	10		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
222	5330	010542582	PACKING-PREFORMED (\$1.90) P/N MIL-R-83248/1-007 & NAS1593-007 (IPV ITEM) F107 BSL 527 BIN A247	100%	1	100%	10		DLA
223	6115	010999786	GENERATOR-DIRECT CURRENT (\$29,862.79) P/N 232-30010/30077-004	100%	1	17%	1.7		FHZ
224	6150	011049271	LEAD-ELECTRICAL (\$12.25) P/N 4F4F/740D-20-16 (IPV ITEM) F107 BSL 458 BIN 3H13	100%	1	0%	0		DLA
225	5331	011121765	O-RING (\$0.33) P/N 10389776/695001250/ (IPV ITEM) F107 BSL 527 BIN A255	100%	2	100%	20		DLA
226	5365	011157425	PLUG-MACHINE THREAD (\$5.29) P/N AS9902-02 (IPV ITEM) F107 BSL 458 BIN 3F13	100%	1	0%	0		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
227	5331	011192008	O-RING (\$0.97) P/N M83248/1-014/004014EM (IPV ITEM) F107 BSL 458 BIN 2G07	100%	2	100%	20		DLA
228	4710	011206304	TUBE-METALLIC (\$31.16) P/N 23928	100%	1	0%	0		DLA
229	2840	011206305	RESTRICTOR-AIRFLOW (\$11.37) P/N 29066	100%	5	4%	2		DLA
230	2840	011206308	RING-INNER (\$460.34) P/N 34426	100%	1	1%	0.1		DLA
231	2840	011206309	SEAL-AIR-AIRCRAFT GAS TURBINE EN (\$1,024.50) P/N 41677/36013 P/N 36013/41677	100%	1	1%	0.1		DLA
232	2840	011206400	SHIELD-HEAT-AIRCRAFT GAS TURBINE (\$31.08) P/N 23430	100%	1	1%	0.1		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
233	3120	011213450	BEARING-SLEEVE (\$628.36) P/N 36125	100%	1	4%	0.4		DLA
234	2840	011215683	RESTRICTOR-AIRFLOW (\$122.80) P/N 29065	100%	15	1%	1.5		DLA
235	2840	011215781	CASE-DIFFUSER-AIRCRAFT GAS TURBI (\$62,111.52) P/N 36370	100%	1	6%	0.6	0	FHZ
236	3110	011237152	BEARING-BALL-ANNULAR (\$2,226.58) P/N 29056/29849/39159	100%	1	10%	1		DLA
237	3110	011237156	BEARING-ROLLER-CYLINDRICAL (\$933.65) P/N 19301/23408/39157	100%	3	10%	3		DLA
238	3110	011237160	BEARING-BALL-DUPLEX (\$1,629.99) P/N 29477/29846/39557	100%	1	100%	10		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
239	8145	011251478	SHIPPING AND STORAGE CONTAINER-E (\$5,296.20) P/N D5310-1	100%	1	0%	0	0	FHZ
240	5305	011260640	SCREW-MACHINE (\$195.25) P/N 29619	100%	2	75%	9		DLA
241	3110	011264316	PLATE-RETAINING-BEARING (\$425.14) P/N 34053	100%	1	20%	2	2	FHZ
242	5331	011264558	O-RING (\$38.82) P/N 22762 <span style="color: blue;">(IPV ITEM)</span> <span style="color: blue;">F107 BSL 458 BIN 2F04</span>	100%	1	0%	0		DLA
243	4730	011266822	STRAINER ELEMENT-SEDIMENT (\$101.73) P/N 22665/501JH	100%	1	4%	0.4		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
244	4730	011266823	STRAINER ELEMENT-SEDIMENT (\$5.70) P/N 22667/503JH	100%	2	4%	0.8		DLA
245	2840	011266878	PLATE-COMPONENT MOUNTING- AIRCRAF (\$612.11) P/N 36854	100%	1	13%	1.3	0	FHZ
246	2840	011266879	DIFFUSER-AIRCRAFT GAS TURBINE EN (\$399.37) P/N 29280	100%	1	0%	0	0	FHZ
247	2915	011266881	ADAPTER ASSEMBLY-ENGINE SERVICE- (\$2,431.20) P/N 23854	100%	1	0%	0	0	FHZ
248	2840	011266884	CASE-COMPRESSOR-AIRCRAFT GAS TUR (\$1,600.98) P/N 29918	100%	1	0%	0	1	FHZ

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
249	2840	011266903	ROTOR-COMPRESSOR-AIRCRAFT GAS TU (\$1,637.21) P/N 23844	100%	1	0%	0	2	FHZ
250	2840	011266904	ROTOR-COMPRESSOR-AIRCRAFT GAS TU (\$2,342.13) P/N 23845	100%	1	0%	0	1	FHZ
251	2840	011266905	ROTOR-COMPRESSOR-AIRCRAFT GAS TU (\$4,022.37) P/N 23490/42528	100%	1	0%	0	1	FHZ
252	2840	011266909	ROTOR-TURBINE-AIRCRAFT GAS TURBI (\$3,562.02) P/N 34984	100%	1	0%	0	0	FHZ
253	2840	011266911	VANE-COMPRESSOR-AIRCRAFT GAS TUR (\$725.31) P/N 23483	100%	1	0%	0	0	FHZ
254	2840	011266914	CASE-COMPRESSOR-AIRCRAFT GAS TUR (\$1,438.05) P/N 34492	100%	1	1%	0.1	0	FHZ



# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
255	2840	011266917	CHAMBER-COMBUSTION-AIRCRAFT GAS (\$1,390.08) P/N 36368	100%	1	37%	3.7	0	FHZ
256	2840	011266918	CONE-EXHAUST AIRCRAFT GAS TURBIN (\$18,928.99) P/N 36868	100%	1	0%	0	0	FHZ
257	2840	011266924	SHAFT-TURBINE-AIRCRAFT GAS TURBI (\$2,794.79) P/N 36387	100%	1	1%	0.1	1	FHZ
258	2840	011266926	VANE ASSEMBLY-COMPRESSOR-AIRCRAF (\$812.92) P/N 34021	100%	1	0%	0	0	FHZ
259	2840	011266927	NOZZLE ASSEMBLY-TURBINE-AIRCRAFT (\$1,011.96) P/N 34022	100%	1	0%	0	1	FHZ
260	3110	011267034	PLATE-RETAINING-BEARING (\$568.14) P/N 36217	100%	1	0%	0	4	FHZ

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
261	3110	011267590	BEARING-BALL-ANNULAR (\$834.71) P/N 34993/M203SSTX88	100%	1	100%	10		DLA
262	3120	011267593	BUSHING-SLEEVE (\$33.88) P/N 34949	100%	1	4%	0.4		DLA
263	2915	011267646	ACCUMULATOR-FUEL SYSTEM (\$8100.60) P/N 33406/34922	100%	1	0%	0		DLA
264	2840	011267650	FITTING-ADAPTER (\$258.27) P/N 23681	100%	1	4%	0.4		DLA
265	2840	011267651	WASHER ASSEMBLY (\$22.80) P/N 23855	100%	1	100%	10		DLA
266	2840	011267655	BRACKET ASSEMBLY (\$143.65) P/N 36126	100%	1	50%	5		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
267	5342	011267656	BRACKET ASSEMBLY (\$596.94) P/N 36119	100%	1	0%	0		DLA
268	2840	011267658	BRACKET ASSEMBLY (\$52.32) P/N 23801	100%	1	4%	0.4		DLA
269	2840	011267659	BRACKET ASSEMBLY (\$41.85) P/N 23806	100%	1	4%	0.4		DLA
270	2840	011267660	RETAINER (\$1.28) P/N 29570	100%	2	4%	0.8		DLA
271	2840	011267661	SUPPORT-STATIC VENT (\$52.37) P/N 36855	100%	1	0%	0		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
272	2840	011267665	SCOOP-LOW PRESSURE (\$299.88) P/N 29588	100%	1	0%	0		DLA
273	5310	011268475	NUT-SELF-LOCKING-ROUND (\$201.90) P/N 22620	100%	1	70%	7		DLA
274	5331	011268476	O-RING (\$47.51) P/N 36919 <span style="color: blue;">(IPV ITEM) F107</span> <span style="color: blue;">BSL 458 BIN 1E02</span>	100%	1	0%	0		DLA
275	5315	011268649	PIN-STRAIGHT-HEADLESS (\$0.69) P/N 36139	100%	1	0%	0		DLA
276	2840	011273196	FLANGE-BELLOWS MOUNTING (\$7.50) P/N 19259	100%	3	4%	1.2		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
277	5305	011268802	SCREW-MACHINE (\$5.97) P/N MS9554-05	100%	31	4%	12.4		DLA
278	5315	011271009	KEY-MACHINE (\$7.63) P/N 22393 <span style="color: blue;">(IPV ITEM)</span> <span style="color: blue;">F107</span> <span style="color: blue;">BSL 458 BIN 3F14</span> <span style="color: blue;">BSL 527 BIN A257</span>	100%	1	0%	0		DLA
279	5315	011271091	KEY P/N 31042 (\$10.41)	100%	1	2%	0.2		DLA
280	3120	11272895	BUSHING-SLEEVE (\$1,363.27) P/N 34682	100%	3	0%	0		DLA
281	2945	011273029	FILTER ELEMENT-FLUID (\$38.25) P/N 23215/426418-2/7584734 <span style="color: blue;">(IPV ITEM)</span> <span style="color: blue;">F107 BSL 458 BIN 2G10</span> <span style="color: blue;">F107</span> <span style="color: blue;">BSL 527 BIN A136</span>	100%	2	38%	7.6		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
282	2840	011273190	FITTING-TUBE (\$136.60) P/N 23683	100%	1	95%	9.5		DLA
283	5342	011273191	BRACKET-ENGINE MOUNT (\$358.42) P/N 36116	100%	1	0%	0		DLA
284	2840	011273192	SHROUD-IGNITER (\$5,660.70) P/N 34380	100%	2	0%	0		DLA
285	2840	011273195	RETAINER-HEAT SHIELD (\$54.09) P/N 29809	100%	8	4%	3.2		DLA
286	2840	011273197	FITTING-PRESSURE (\$135.92) P/N 29459	100%	1	4%	0.4		DLA

## F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
287	2840	011273200	SEAL-LABYRINTH (\$912.99) P/N 34633	100%	1	4%	0.4		DLA
288	2840	011273341	CASE-TURBINE-AIRCRAFT GAS TURBIN (\$67.47) P/N 24927	100%	1	0%	0		DLA
289	4730	011273519	MANIFOLD-AIR LINE (\$470.00) P/N 23828	100%	1	4%	0.4		DLA
290	5306	011273733	BOLT-MACHINE (\$1.79) P/N AS9556-03/MS9556-03	100%	1	4%	0.4		DLA
291	5310	011274443	WASHER-RECESSED (\$12.26) P/N 22406	100%	1	74%	7.4		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
292	2840	011274689	ELBOW ASSEMBLY (\$438.38) P/N 23815	100%	1	74%	7.4		DLA
293	2840	011274690	BRACKET-SENSOR (\$20.49) P/N 36062	100%	1	1%	0.1		DLA
294	3040	011274757	GEARSHAFT-SPUR (\$1,400.15) P/N 27683	100%	1	4%	0.4		DLA
295	5305	011277075	SCREW-MACHINE (\$223.95) P/N MS9487-02	100%	2	0%	0		DLA
296	5331	011278065	O-RING (\$0.57) P/N M83248/2-033 & MIL-R- 83248/2	100%	1	37%	3.7		DLA
297	5305	011284073	SCREW-MACHINE (\$2.16) P/N 872-0124-175/MS9488-04	100%	2	0%	0		DLA



# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
298	5306	011287074	BOLT-SHOULDER P/N 29548 (\$16.42) (IPV ITEM) F107 BSL 458 BIN 3J06 BSL 527 BIN A133	100%	1	69%	6.9		DLA
299	5310	011287083	NUT-SELF-LOCKING-EXTENDED WASHER (\$23.89) P/N 29221/H50699-9	100%	1	70%	7		DLA
300	5330	011287085	GASKET (\$156.33) P/N 36539/798333-A	100%	1	34%	3.4		DLA
301	2840	011287246	BOSS-THERMOCOUPLE (\$9.55) P/N 36654	100%	3	2%	0.6		DLA
302	2840	011287247	STRUT-HOUSING (\$15.95) P/N 29391	100%	3	0%	0		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
303	4710	11287999	TUBE-GAS START (\$163.92) P/N 36956	100%	1	4%	0.4		DLA
304	5330	011288036	PACKING ASSEMBLY (\$1,443.52) P/N 27898/5-2626-1	100%	1	31%	3.1		DLA
305	5330	011288037	PACKING ASSEMBLY (\$116.45) P/N 2-838- 23/27686/39169/39531	100%	2	56%	11.2		DLA
306	5330	011288045	RETAINER-PACKING (\$182.46) P/N 24878/39532/47285	100%	2	68%	13.6		DLA
307	5330	011288224	GASKET (\$577.94) P/N 29617/50527/778102	100%	1	0%	0		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
308	5330	011288225	GASKET (\$189.37) P/N 24989/808118	100%	1	34%	3.4		DLA
309	5330	011288226	PACKING WITH RETAINER (\$556.26) P/N 22237/23627/43082	100%	2	59%	11.8		DLA
310	5330	011288227	PACKING WITH RETAINER (\$605.34) P/N 24044/B-108430	100%	1	68%	6.8		DLA
311	5340	011288236	BRACKET-ANGLE (\$7.82) P/N 23616	100%	1	1%	0.1		DLA
312	5340	011288238	BRACKET-ANGLE (\$14.09) P/N 23615	100%	1	0%	0		DLA
313	5307	011288240	STUD-SELF-LOCKING P/N 36653 (\$69.16)	100%	6	5%	3	0.39	DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
314	4710	011288435	TUBE ASSEMBLY-METAL-BRANCHED P/N 36646 (\$573.72)	100%	1	4%	0.4		DLA
315	5325	011288590	RING-RETAINING P/N 22536 (\$141.84)	100%	6	1%	0.6		DLA
316	5340	011288595	STRAP-RETAINING P/N 29607 (\$26.13)	100%	8	0%	0		DLA
317	5365	011288604	SHIM P/N 22447 (\$75.13)	100%	1	50%	5		DLA
318	5365	011288605	SHIM P/N 22448 (\$16.39)	100%	1	50%	5		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
319	5365	011288606	SHIM P/N 22449 (\$28.34)	100%	1	50%	5		DLA
320	5365	011288610	SHIM P/N 22453 (\$24.59)	100%	1	50%	5		DLA
321	5365	011288612	SPACER-RING P/N 27620 (\$136.60)	100%	1	1%	0.1		DLA
322	4710	011288620	TUBE ASSEMBLY-METAL P/N 36555 (\$122.26)	100%	1	4%	0.4		DLA
323	4710	011288625	TUBE ASSEMBLY-METAL P/N 36841 (\$511.24)	100%	1	0%	0		DLA
324	4710	011288626	TUBE ASSEMBLY-METAL P/N 36559 (\$539.57)	100%	1	4%	0.4		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
325	4710	011288628	TUBE ASSEMBLY-METAL P/N 34735 (\$48.85)	100%	1	4%	0.4		DLA
326	5305	011288921	SCREW-MACHINE P/N MS9564-11 (\$5.17)	100%	1	1%	0.1		DLA
327	6150	011289078	LEAD-ELECTRICAL P/N 740D-21-16/BAC-J40D-21-16 (\$19.97) <i>(IPV ITEM)</i> F107 BSL 458 BIN 3G01	100%	1	70%	7		DLA
328	5331	011293137	O-RING P/N 182591/3-902L1218-80 (\$0.87) <i>(IPV ITEM)</i> F107 BSL 458 BIN 3F10	100%	1	70%	7		DLA
329	5331	011293140	O-RING P/N 3-905L1007-80/3-905L1218-80/M25988/4-905 (\$0.28) <i>(IPV ITEM)</i> F107 BSL 458 BIN 3F08	100%	1	0%	0		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
330	5331	011293145	O-RING P/N 3-904L806-80/3-904(L1007-80)/904-11648 (\$0.24) <span style="color: blue;">(IPV ITEM)</span> <span style="color: blue;">F107 BSL 458 BIN 3F15</span>	100%	1	1%	0.1		DLA
331	4820	011294547	COCK-DRAIN P/N 1819-3/23200 (\$368.82)	100%	1	4%	0.4		DLA
332	3020	011294690	GEAR-BEVEL P/N 24882 (\$262.41)	100%	1	4%	0.4		DLA
333	3020	011294692	GEAR-SPUR P/N 27690 (\$4,712.70)	100%	1	4%	0.4		DLA
334	4710	011297542	TUBE ASSEMBLY-METAL P/N 36561 (\$184.41)	100%	1	4%	0.4		DLA

## F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
335	5310	011297611	NUT-PLAIN-ROUND P/N 24917 (\$24.71)	100%	1	1%	0.1		DLA
336	2840	011299334	INSULATION BLANKET-THERMAL- AIRCR P/N 303H28702/34733 (\$15.03)	100%	1	4%	0.4		DLA
337	6620	011302250	TRANSMITTER-RATE OF FLOW P/N 210-C-23401/2215-00-1019- 1/34966 (\$1,518.52)	100%	1	5%	0.5	0	FHZ
338	4730	011304356	COUPLING-TUBE P/N 29973 (\$111.63)	100%	2	2%	0.4		DLA
339	4730	011306523	REDUCER-TUBE P/N 22654 (\$50.16)	100%	1	1%	0		DLA



# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
340	2840	011309634	BELLOWS-TURBINE NOZZLE P/N 00-1633-001- C/19286/72051/B41644 (\$120.82)	100%	3	4%	1.2		DLA
341	5325	011311862	RING-RETAINING P/N 22275/UR168-S (\$0.69)	100%	1	2%	0.2		DLA
342	5310	011312240	NUT-PLAIN-HEXAGON P/N MS9553-06 (\$5.54)	100%	1	1%	0.1		DLA
343	5310	011314715	WASHER-KEY P/N MS9276-08 (\$0.36) <a href="#">(IPV ITEM)</a> <a href="#">F107 BSL 458 BIN 3J08</a> <a href="#">BSL 527 BIN A087</a>	100%	6	98%	58.8		DLA
344	1420	011315093	GENERATOR-ELECTRONIC COMMAND SIG (\$17970.92) P/N 10-614515-1 REV/ 29916.44340	100%	1	19%	1.9		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
345	5305	011321039	SCREW-MACHINE P/N MS9564-24 (\$202.90)	100%	4	0%	0		DLA
346	5305	011321040	SCREW-MACHINE P/N MS9564-15 (\$272.11)	100%	1	0%	0		DLA
347	4730	011325756	NIPPLE-TUBE P/N 29121/JCM-15213-003/R44182P-04 (\$27.73)	100%	2	4%	0.8		DLA
348	5305	011337915	SCREW-MACHINE P/N MS9563-07 (\$223.58)	100%	3	0%	0		DLA
349	5325	011356034	INSERT-SCREW THREAD P/N 29568/SR1661 (\$18.04)	100%	63	0%	0		DLA
350	2925	011360478	IGNITER-SPARK-JET ENGINE P/N 10-630350/23696 (\$1,010.16)	100%	2	55%	11		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
351	2840	011426580	TUBE-TRANSFER P/N 27499 (\$48.63)	100%	3	0%	0		DLA
352	3110	011433793	BEARING-ROLLER-CYLINDRICAL P/N 36017/39168/39500 (\$1,128.70)	100%	1	13%	1.3		DLA
353	3040	011433831	BRACKET-ANTIROTATION P/N 36962 (\$94.25)	100%	2	2%	0.4		DLA
354	2840	011433832	RUNNER-SEAL P/N 37908 (\$732.31)	100%	1	4%	0.4		DLA
355	2840	011433835	RETAINER ASSEMBLY P/N 36828 (\$9.45)	100%	1	4%	0.4		DLA
356	4730	011439466	CAP-TUBE P/N 2-02813-8/4690009-08/AFP241-08 (\$20.49) <span style="color: blue;">(IPV ITEM)</span> <span style="color: blue;">F107 BSL 458 BIN 3E02</span>	100%	1	0%	0		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
357	2840	011444686	HOUSING-GEARBOX-TURBINE ENGINE P/N 29614/37223 (\$3,177.13)	100%	1	0%	0	1	FHZ
358	5330	011452096	SLEEVE-SEAL-COUPLER P/N 37005 (\$47.21)	100%	1	90%	9		DLA
359	5360	011463171	SPRING P/N 23799 (\$237.45)	100%	2	68%	13.6		DLA
360	2840	011528488	CASE AND NOZZLE ASSEMBLY-TURBINE P/N 37314 (\$12,383.14)	100%	1	0%	0	0	FHZ
361	5330	011560238	GASKET P/N 37220 (\$201.56)	100%	1	33%	3.3		DLA
362	2995	011575369	INSULATION START CARTRIDGE P/N 34363 (\$280.39)	100%	1	94%	9.4		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
363	2840	011584261	DUCT-EXHAUST-AIRCRAFT GAS TURBIN P/N 37323 (\$17,767.81)	100%	1	3%	0.3	0	FHZ
364	2840	011584263	GEARBOX-ACCESSORY DRIVE-TURBINE P/N 37371 (\$18,633.65)	100%	1	0%	0	0	FHZ
365	2840	011585873	BOSS ASSEMBLY-GEARBOX DUCT P/N 37318 (\$1,639.20)	100%	1	4%	0.4		DLA
366	2840	011585874	FLANGE-BEARING TUBE P/N 37045 (\$136.60)	100%	1	0%	0		DLA
367	2840	011585875	SEAL-BYPASS DUCT P/N 38717 (\$15.15)	100%	1	4%	0.4		DLA
368	2840	011585876	PRIMARY PLATE-ASSEMBLY P/N 36837 (\$532.74)	100%	1	1%	0.1		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
369	2840	011585877	ADAPTER-GEARBOX P/N 37381 (\$68.30)	100%	1	1%	0.1		DLA
370	2840	011585878	FITTING-GEARBOX P/N 37264 (\$187.83)	100%	1	1%	0.1		DLA
371	2840	011585960	HOUSING-GEARBOX-TURBINE ENGINE P/N 37372 (\$6,512.36)	100%	1	0%	0		FHZ
372	2840	011585961	HOUSING-GEARBOX-TURBINE ENGINE P/N 37373 (\$3,061.00)	100%	1	0%	0	0	FHZ
373	2840	011585962	HOUSING-GEARBOX-TURBINE ENGINE P/N 37362/37374 (\$1,194.42)	100%	1	0%	0	0	FHZ
374	2840	011585963	NOZZLE-TURBINE-AIRCRAFT GAS TURB P/N 37269 (\$12,383.14)	100%	1	31%	3.1	2	FHZ

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
375	2840	011585964	SHIELD-HEAT-AIRCRAFT GAS TURBINE 37271 (\$304.62) P/N	100%	1	1%	0.1		DLA
376	2840	011590203	ELBOW-GEARBOX (\$160.00) P/N 37321/37389	100%	1	1%	0.1		DLA
377	4720	011600824	HOSE-AIR DUCT (\$16.32) P/N 37469/GG718	100%	1	81%	8.2		DLA
378	6150	011606489	WIRING HARNESS-BRANCHED (\$5774.16) P/N 36347	100%	1	3%	0.3	0	FHZ
379	4710	011606619	TUBE ASSEMBLY-METAL P/N 36560 (\$117.26)	100%	1	4%	0.4		DLA
380	4710	011606620	TUBE ASSEMBLY-METAL P/N 37256 (\$36.36)	100%	1	6%	0.6		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
381	3020	011609354	GEAR-SPUR P/N 37376 (\$945.83)	100%	1	0%	0	0	FHZ
382	5330	011612255	GASKET P/N 38716 (\$54.11)	100%	1	1%	0.1		DLA
383	3130	011615887	HOUSING-BEARING UNIT P/N 49338/37430 (\$1,277.46)	100%	1	1%	0.1		DLA
384	5340	011635898	PLATE-T P/N 37311 (\$21.44)	100%	1	0%	0		DLA
385	4730	011647268	RESTRICTOR-FLUID FLOW (\$9.00) P/N 36845	100%	1	1%	0.1		DLA
386	5331	011692891	O-RING (\$0.27) P/N 182641/3-903L806-80 (IPV ITEM) F107 BSL 458 BIN 3F05	100%	2	20%	4		DLA



# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
387	5330	011792283	GASKET (\$55.56) P/N P21-473-36-CL	100%	1	0%	0		DLA
388	5320	011976644	PIN-RIVET (\$33.91) P/N BACB30FM8A5SU	100%	1	1%	0.1		DLA
389	5340	012199222	CLAMP-LOOP (\$2.13) P/N 90595/NAS1715C10K	100%	1	8%	0.8		DLA
390	5340	012199223	CLAMP-LOOP (\$0.58) P/N 90589/NAS1715C2K	100%	1	7%	0.7		DLA
391	5340	012203536	BRACKET-ANGLE (\$2.99) P/N 91611/MS9600-016	100%	1	1%	0.1		DLA
392	5306	012208664	BOLT-MACHINE (\$10.30) P/N 91427/MS9488-07	100%	2	4%	0.8		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
393	4710	012251127	TUBE ASSEMBLY-METAL (\$170.75) P/N 39209	100%	1	4%	0.4		DLA
394	5340	012298447	CAP-PROTECTIVE-DUST AND MOISTURE P/N 36274/700-12 (\$4.18) (IPV ITEM) F107 BSL 458 BIN 1E03	100%	1	5%	0.7		DLA
395	5365	012305295	SPACER-RING P/N 36141-01 (\$9.11) (IPV ITEM) F107 BSL 458 BIN 2E05	100%	1	5%	0.7		DLA
396	5365	012305297	SPACER-RING (\$29.81) P/N 36141-03	100%	1	33%	3.3		DLA
397	5365	012313460	SPACER-RING (\$29.60) P/N 36141-09 P/N 36141-09	100%	1	33%	3.3		DLA
398	5365	012316022	SPACER-RING (\$33.32) P/N 36141-04	100%	1	4%	0.4		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
399	5365	012316023	SPACER-RING (\$7.99) P/N 36141-05	100%	1	4%	0.4		DLA
400	5365	012316024	SPACER-RING (\$41.69) P/N 36141-06	100%	1	4%	0.4		DLA
401	5365	012316027	SPACER-RING (\$210.36) P/N 36141-10	100%	1	4%	0.4		DLA
402	4730	012389078	CLAMP-HOSE (\$5.76) P/N NAS1922-0125-3H/NAS1923	100%	1	0%	0		DLA
403	5340	012442719	CAP-PROTECTIVE-DUST AND MOISTURE (\$6.40) P/N 1000-14/36279	100%	1	4%	0.4		DLA
404	5305	012479054	SCREW-MACHINE (\$7.39) P/N 003-008548-019/NAS1635-06-30	100%	1	5%	0.5		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
405	2915	012508692	FILTER-FLUID (\$614.65) P/N 26945/39208	100%	1	100%	10		DLA
406	5340	012705503	CAP-PROTECTIVE-DUST AND MOISTURE (\$0.27) P/N 1.062-8/36283	100%	1	1%	0.1		DLA
407	5340	012715214	CLAMP-LOOP (\$2.99) P/N NAS1715CT16K	100%	1	7%	0.7		DLA
408	5935	012719984	COVER-ELECTRICAL CONNECTOR (\$64.20) P/N 2411122/38226	100%	2	1%	0.2		DLA
409	5365	012963307	SPACER-RING (\$15.11) P/N 23514-01	100%	1	33%	3.3		DLA
410	5365	012963309	SPACER-RING (\$13.82) P/N 23514-03	100%	1	4%	0.4		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
411	5365	012963310	SPACER-RING (\$20.08) P/N 23514-04	100%	1	4%	0.4		DLA
412	5365	012963314	SPACER-RING (\$17.48) P/N 23514-08	100%	1	4%	0.4		DLA
413	5307	016514546	Stud, Locked (\$0.0) P/N SFC1905UM-10	100%	3	4%	1.2		DLA
414	5342	012980873	COVER-PROTECTIVE- GENERATOR (\$29.93) P/N 46398	100%	1	1%	0.1		DLA
415	5342	012980874	COVER-PROTECTIVE- GENERATOR (\$46.42) P/N 46397/9040973	100%	1	1%	0.1		DLA
416	3110	013017664	BEARING-BALL-ANNULAR (\$159.63) P/N 1906S-14-ST/27100/29843	100%	2	12%	2.4		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
417	3110	013017665	BEARING-BALL-ANNULAR (\$588.22) P/N 1903S-11- ST/23410/27099/39161/46738	100%	4	5%	2		DLA
418	5340	013373190	PLUG-PROTECTIVE-DUST AND MOISTUR (\$279.65) P/N 82-2443	100%	1	1%	0.1		DLA
419	5310	013522752	WASHER-FLAT (\$1.28) P/N 10122225/38-18416-0008- 0/4915831-13 (IPV ITEM) F107 BSL 458 BIN 3E04 BSL 508 BIN 4B07	100%	1	10%	1		DLA
420	5330	013558643	GASKET (\$34.73) P/N 362-527-9006/VD261-0006- 0006	100%	1	70%	7		DLA
421	5331	013666214	O-RING P/N 3-914V747-75/501-1793 PC. NO. 21 (\$0.27) (IPV ITEM) F107 BSL 458 BIN 2J05	100%	1	20%	2		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
422	5330	013850642	PACKING-PREFORMED P/N M25988/2-010 & MIL-R-25988/2 (\$0.36) <span style="color: blue;">(IPV ITEM)</span> <span style="color: blue;">F107 BSL 527 BIN A260</span>	100%	1	100%	10		DLA
423	4730	014500250	CAP-TUBE (\$30.20) P/N 6419910/6419910-1/AN929-4J	100%	1	1%	0.1		DLA
424	5325	015475478	RING-Retaining (\$7.30) P/N M27426-3174B	100%	1	1%	0.1		DLA
425	5331	015481474	O-RING (\$1.42) P/N 516-5486651 ITEM F70/M83248/1-912 & M83248/1-912CP	100%	1	1%	0.1		DLA
426	5325	015784056	RING-RETAINING (\$0.30) P/N MS16625-4025	100%	1	68%	6.8		DLA
427	4730 Alt: 4730	011336599 Alt: 016103424	SLEEVE,FLARED,TUBE FITTING (\$5.81) P/N DY90-N3 / 29092	100%	8	70%	56		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
428	5331	001660990	O-RING (\$0.16) P/N M83248/1-014/039-705-0002/040-0140-00-0	100%	2	10%	2		DLA
429	5331	001675173	O-RING (\$0.10) P/N 000908/028-07443/10086594 (IPV ITEM)	100%	1	10%	1		DLA
430	5325	001827020	RING,RETAINING (\$2.96) P/N M27426-3173D/G-RR-312S/M27426-3173D	100%	1	0%	0		DLA
431	5315	003545521	KEY,WOODRUFF (\$3.70) P/N 108A902855/A03955/MS9841-01	100%	1	1%	0.1		DLA
432	4730	003974432	SEAL,CONICAL,FLARED (\$9.19) P/N AO100N-05/SECO7N5/ST2284-05	100%	4	2%	0.8		DLA
433	4730 Alt. 4730	004359482 // 013956595	SLEEVE,COMPRESSION (\$1.66) P/N AP50N-06/AP50N6/AS3074-06	100%	2	0%	0		DLA



# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
434	4730	010707964	SEAL, CONICAL, FLARED (\$7.85) P/N 29095/DY90/DY90-N-6L/SECO 7N	100%	1	1%	0.1		DLA
435	5331	010797299	O-RING (\$0.18) P/N M25988/2-016 & MIL-R- 25988/2	100%	#N/A	0%	#N/A		DLA
436	5331	010797300	O-RING (\$0.24) P/N M25988/2-017 & MIL-R- 25988/2	100%	#N/A	0%	#N/A		DLA
437	5331	10797305	O-RING (\$0.21) P/N C10762-0070-0013/M25988/2- 013	100%	#N/A	0%	#N/A		DLA
438	5340	010823004	CAP, PROTECTIVE, DUST (\$0.03) P/N AIA/NAS832 & M5501/11-F4	100%	#N/A	0%	#N/A		DLA
439	5315	011027476	PIN, COTTER (\$0.37) P/N 69272-23	100%	#N/A	0%	#N/A		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
440	3110	013017665	BEARING,BALL,ANNULA (\$588.22) P/N 46738//1903S-11- ST//23410//27099	100%	4	1%	0.4		DLA
441	3110	011237154	BEARING,BALL,ANNULA (\$115.41) P/N 1906S-14-ST/27100/29843	100%	0	0%	0		DLA
442	2840	011266910	ROTOR,TURBINE,AIRCRAFT GAS TURBINE ENGINE (\$26,062.31) P/N 34469	100%	#N/A	0%	#N/A		FHZ
443	2840	011266921	HOUSING, GEARBOX, TURB (\$3,061.00) P/N 23692	100%	1	0%	0	0	FHZ
444	5307	011269400	STUD,LOCKED IN (\$25.26) P/N 88180	100%	3	0%	0		DLA
445	2840	011273199	RETAINER ASSEMBLY (\$1,931.95) P/N 23933	100%	1	4%	0.4		DLA
446	5340	016516058	Clamp, Outboard, Oil Tube (\$2.88) P/N 36501	100%	1	0%	0		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
447	5331	011292019	O-RING (\$0.31) P/N M25988/4- 017//10117163//12A037-20- 1//1354-146 (IPV ITEM) F107 BSL 458 BIN 3H02	100%	#N/A	0%	#N/A		DLA
448	5365	011302486	SPACER,RING P/N 23514-09 (\$7.42)	100%	1	0%	0		DLA
449	5310	011312240	NUT,PLAIN,HEXAGON (\$5.54) P/N MS9553-06	100%	1	0%	0		DLA
450	5331	011560092	O-RING (\$0.22) P/N M25988/4-014//014- 11648//10117174//13-09-014 (IPV ITEM) F107 BSL 458 BIN 1J02	100%	#N/A	0%	#N/A		DLA
451	5320	011805227	RIVET,BLIND (\$0.04) P/N M24243/1G402 (IPV ITEM) F107 BSL 458 BIN 2E03	100%	#N/A	0%	#N/A		DLA

## F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calculated MDR		DLA / FHZ
452	5307	011850450	STUD,LOCKED IN (\$10.97) P/N 88082//9117M42P05/SFC250SU M-15	100%	2	10%	2		DLA
453	2915	011896033	PLUNGER (\$68.10) P/N 3330-036	100%	1	0%	0		DLA
454	2915	011896034	SPACER (\$8.93) P/N 3432-024	100%	1	0%	0		DLA
455	2915	011896035	SLEEVE,FUEL SHUTOFF (\$91.25) P/N 3315-090/3515-090	100%	1	0%	0		DLA
456	4320	012005321	PLUG FILLER DIPSTIC (\$295.43) P/N RD36942A	100%	1	0%	0		DLA
457	5340	013284436	COVER,ACCESS (\$56.23) P/N 46397//10-516451-1	100%	#N/A	0%	#N/A		DLA

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calcula ted MDR		DLA / FHZ
458	5310	013529593	WASHER,FLAT (\$2.64) P/N 071005/10335584/98017A140 (IPV ITEM) F107 BSL 458 BIN 3H04	100%	1	0%	0		DLA
459	5307	016514531	STUD,LOCKED IN (\$57.41) P/N 88033/SFC190SUM-14	100%	1	10%	1		DLA
460	5307	016514536	STUD,LOCKED IN (\$12.54) P/N 88031/SFC190SUM-12	100%	11	1%	1.1		DLA
461	5315	016523947	PIN,SHOULDER,HEADLE (\$17.86) P/N 88082	100%	1	0%	0		DLA
462	5331	000200186	O-RING (\$0.13) (IPV Item) F107 BSL 458 BIN 2J02 BSL 527 BIN A090 P/N 028-07422	100%	1	20%	2		DLA

Transferring from Plain with updated Requirements

# F107 MATERIAL BOM

	FSC Component	CompNiin	Noun	Occurance Rate	QPA	Std Repl Pct, Prod	Calcula ted MDR		DLA / FHZ
--	------------------	----------	------	-------------------	-----	-----------------------	-----------------------	--	--------------

DRAFT